

**Engineering Bulletin: TD80 with P2000A on Some Newer Intellitrol Racks**  
(2010-06-28)

Re: Failure to permit loading when using the TD80 / P2000A.

Dear Customers,

Recently, we have received reports that the TD80 / P2000A combination has not permitted loading at two loading racks that use recently manufactured Scully Intellitrol overfill prevention control units. Users of the P2000A will likely experience issues with these newer Intellitrol based racks. Titan Logix has prepared this bulletin to alert users to this possibility.

We are actively investigating the reasons for this issue and developing solutions to help our customers resolve this problem.

As more information becomes available this bulletin will be updated.

Customers who have questions or concerns about this bulletin should call their Sales Representative at (877) 462-4085.

Titan Logix has developed transport gauging systems for our customers for many years and looks forward to continuing to provide the leading level gauging system for transport tankers. Thank you for your continued support.

Sincerely,



Ron Willis, PEng, EE  
Chief Engineer